CERCLA REMOVAL ACTION DAILY WORK ORDER

SITE NAME: BCF OIL REFINING

CONTRACT NO. 68-S2-99-07 DATE(s):2/16/01

RM: J.D'Angelo/B.Moody

ORDER NO.: 19

EPA REGION: II

SITE/SPILL NO.: PU

MONITORS: Paul Potvin

SHIFT:0700 - 1530 OSC: Thomas P.Budroe

CONTRACTOR: WRS Infras.& Env., Inc.

WORK ORDER #63

DESCRIPTION OF WORK TO BE PERFORMED

1) Provide form 1900-55s to the OSC for approval.

- 2) Continue providing 24 hour security for the Site. One person acting as the guard will be on-site at all times. Each guard will work an eight hour shift. Each guard will key-in at the appropriate time and location at each key-box. The guard will periodically inspect the site for any releases, spills, leaks, fires, etc.
- 3) Conduct daily safety briefing.
- 4) Continue heating tank 9 with steam as appropriate.
- 5) Load tank trucks with oil from the appropriate tanks and from the appropriate drums staged on Site and complete all necessary shipping paperwork (manifest). Construct a loading/containment area prior to loading this material.
- 6) Complete a Daily Work Summary outlining daily accomplishments.
- 7) Procure an oil/water separator and coalescer for pre-treating the aqueous waste.
- 8) Procure a qualified subcontractor to remove and dispose of the asbestos on the pipe in the back room of the boiler house.
- 9) Load contaminated water from the appropriate tanks for disposal.
- 10) Pretreat and dispose of the aqueous waste in underground tanks 15 and 16.
- 11) Remove all surface pipes, pumps and other appurtenances (using the excavator when necessary) overlaying tanks 15 and 16.
- 12) Obtain bids for the stabilizing agent to be used to stabilize the tank sludge.
- 13) Remove all other liquid wastes from tanks 15 and 16.
- 14) Remove and stage the soil overlaying USTs 15 and 16 and cut the tops off USTs 15 and 16.
- 15) Determine the most cost effective means of disposing of the oil/water emulsion material in tank trailer 106 currently at the Safety Kleen facility in Deer Park, Texas.
- 16) Remove the Sludge from tanks 15 and 16, stabilize and ship for disposal.
- 17) Obtain waste delivery confirmation from Safety Kleen and provide same to EPA.
- 18) Conduct other tasks as necessary in preparation of loading the waste materials on Site into trucks for disposal.

NUMBER OF PERSONNEL AUTHORIZED

1-RESPONSE MANAGER 0-FOREMAN 5-CLEANUP TECHNICIAN(S) 1-PCT 0-CHEMIST 0-EQUIPMENT OPERATOR 0-LAB TECH 0-T&D Coordinator

CERCLA REMOVAL ACTION DAILY WORK ORDER

SITE NAME: BCF OIL REFINING		CONTRACT NO	CONTRACT NO. 68-S2-99-07	
ORDER NO.: 19			DATE(s):2/16/01	
SITE/SPILL NO.: PU		·	SHIFT:0700 - 1530	
EPA REGION: II		OSC: Thomas	OSC: Thomas P.Budroe	
CONTRACTOR: WRS Infras.&	Env., Inc	. WORK ORDER	<u>#63</u>	
MONITORS: Paul Potvin		RM: J.D'And		
			-	
EQUIPMENT AND EXPENDABLE MATERIALS AUTHORIZED				
ITEM	OUANT.	ITEM	QUANT.	
PICK UP TRUCK (1/4 TON)	4	FAX	1	
OVERPACKS	.0	RADIO HAND HELD	3	
EXCAVATOR	<u> -ه- 1</u>	LAPTOP COMPUTER		
PORTABLE BOILER	1	COMPUTER PRINTER AIR COMPRESSOR		
DOUBLE DIAPHRAGM PUMP			1	
PHOTOCOPIER	1	CELLULAR TELEPHO	NE 1	
I CERTIFY THAT THE ABOVE WORK IS ORDERED AND AUTHORIZED BY THE CONTRACTOR IN THE PERFORMANCE OF THE ABOVE CITED DELIVERY ORDER SIGNATURE OF ON-SCENE COORDINATOR				
I ACKNOWLEDGE RECEIPT OF THIS WORK ORDER.				
I ACKNOWLEDGE RECEIPT OF THIS WORK ORDER.				
signature of contractor's representative Whih				
BIGNATURE OF CONTRACTOR'S REPRESENTATIVE WOUNTY				
l III III III III III III III III III I				
DESCRIPTION OF SUPPLIES REQUIRED				
			·	
Amendments:				
<u> </u>				
SIGNATURE OF ON-SCENE CO	ORDINATOR			
SIGNATURE OF CONTRACTOR!	S REPRESEI	NTATIVE		